



- 1 Bubbler
- 2 Brass coupling
- 3 Copper 45 deg elbow
- 4 Brass 90 deg elbow
- 5 3/8 woven ss supply line
- 6 bowl
- 7 Drain & screw
- 8 Rubber washer
- 9 SS drain coupling
- 10 1-1/2" ABS drainline
- 11 SS hose clamp
- 12 Flextube drainline
Can be looped for P-trap
- 13 Button head screws (4)
- 14 SS access plate
- 15 Galvanized baseplate
- 16 3/8" Loop inserts
- 17 3/8" stovebolts
- 18 1-1/2" ABS Coupling

Installation notes

SS suply line has compression fitting.
Use 1/2" to 3/8" reducer for waterline

Flextube line can be looped as P-trap.

Baseplate can be mounted with loop inserts, cast in bolts, or anchor inserts (not supplied with fountain)